

Tabla de referencia - Uniones Rápidas

Equipos de control de presión | Información técnica

| Tipo de Rosca | Diámetro de sello | Diámetro interno | Presión | Servicio | Tamaño de O-ring |
|--------------------------------------|-------------------|------------------|---------|----------|------------------|
| TIPO OTIS | | | | | |
| 5.000-4 | 3.500 | 2.500 / 2.920 | 10,000 | STD | 306-3038-000 |
| 5.000-4 | 3.500 | 2.500 / 2.920 | 5,000 | H2S | 306-3038-000 |
| 5.000-4 | 3.500 | 2.500 / 3.000 | 10,000 | STD | 306-2036-000 |
| 5.000-4 | 3.500 | 2.500 / 3.000 | 5,000 | H2S | 306-2036-000 |
| 5.000-4 | 3.500 | 2.500 | 15,000 | H2S | 306-3038-000 |
| 5.750-4 | 4.000 | 3.000 | 10,000 | H2S | 306-3042-000 |
| 6.000-4 | 4.875 | 4.000 | 5,000 | STD | 306-3049-000 |
| 6.250-4 | 4.000 | 2.500 | 15,000 | H2S | 306-3042-000 |
| 6.500-4 | 4.750 | 3.000 | 10,000 | H2S | 306-3048-000 |
| 6.500-4 | 4.750 | 4.000 | 5,000 | H2S | 306-3048-000 |
| 6.500-4 | 5.188 | 4.000 | 5,000 | H2S | 306-2049-000 |
| 6.500-4 | 5.250 | 4.000 | 5,000 | H2S | 306-3052-000 |
| 7.500-4 | 5.500 | 3.000 | 15,000 | H2S | 306-3054-000 |
| 8.250-4 | 6.188 | 5.125 | 10,000 | H2S | 306-4034-000 |
| 8.250-4 | 6.188 | 5.000 | 10,000 | STD | 306-4034-000 |
| 8.250-4 | 6.188 | 5.000 | 5,000 | H2S | 306-4034-000 |
| 8.375-4 | 5.250 | 4.000 | 10,000 | H2S | 306-4027-000 |
| 8.750-4 | 7.500 | 6.375 | 5,000 | H2S | 306-4041-000 |
| 9.000-4 | 6.750 | 5.000 | 10,000 | H2S | 306-4038-000 |
| 9.500-4 | 8.000 | 6.375 | 5,000 | H2S | 306-4043-000 |
| 9.500-4 | 6.250 | 4.000 | 15,000 | H2S | 306-4035-000 |
| 11.500-4 | 8.250 | 6.375 | 10,000 | H2S | 306-4044-000 |
| 12.000-4 | 10.313 | 9.000 | 5,000 | H2S | 306-4048-000 |
| 12.250-4 | 7.000 | 5.125 | 15,000 | H2S | 306-4039-000 |
| UNIONES LIVIANAS Y DE HUNTING | | | | | |
| 4.750-4 x 2 | 3.750 | 3.000 | 10,000 | H2S | 306-3040-000 |
| 6.125-4 x 2 | 4.750 | 4.060 | 10,000 | H2S | 306-3048-000 |
| 6.875-4 | 5.250 | 4.000 | 6,500 | H2S | 306-3052-000 |
| 7.875-4 x 2 | 6.125 | 5.125 | 10,000 | H2S | 306-3059-000 |
| 9.500-4 x 2 | 6.250 | 4.000 | 15,000 | H2S | 306-4035-000 |
| 11.500-4 | 8.625 | 7.375 | 5,000 | H2S | 306-4045-000 |
| 12.000-4 x 2 | 10.250 | 9.000 | 5,000 | H2S | 306-3076-000 |
| 12.875-4 | 10.625 | 9.000 | 6,500 | H2S | 306-4049-000 |
| 14.125-4 x 2 | 9.000 | 7.062 | 15,000 | H2S | 306-1412-001 |

→ Continúa al dorso

Tabla de referencia - Uniones Rápidas

Equipos de control de presión | Información técnica

| TIPO BOWEN | | | | | |
|--------------|--------|---------------|--------|-----|--------------|
| 4.750-4 | 3.750 | 3.000 | 5,000 | H2S | 306-3040-000 |
| 4.750-4 | 3.750 | 3.000 | 10,000 | STD | 306-3040-000 |
| 5.500-4 x 2 | 4.375 | 3.000 | 5,000 | H2S | 306-3045-000 |
| 5.500-4 x 2 | 4.375 | 3.000 | 10,000 | STD | 306-3045-000 |
| 6.000-4 x 2 | 4.875 | 3.000 | 5,000 | H2S | 306-3049-000 |
| 6.312-4 | 4.375 | 2.500 / 3.000 | 10,000 | H2S | 306-3045-000 |
| 6.312-4 | 3.750 | 2.500 | 15,000 | H2S | 306-3040-000 |
| 6.312-4 | 4.375 | 3.000 | 10,000 | H2S | 306-2042-000 |
| 7.000-5SA | 5.250 | 4.000 | 5,000 | H2S | 306-4027-000 |
| 7.000-5SA | 4.375 | 3.000 | 15,000 | H2S | 306-3045-000 |
| 8.250-4 x 2 | 6.000 | 4.000 | 10,000 | H2S | 306-2056-000 |
| 8.250-4 x 2 | 6.750 | 5.000 | 5,000 | H2S | 306-4038-000 |
| 8.8750-4 x 2 | 6.500 | 5.000 | 10,000 | H2S | 306-4037-000 |
| 9.875-4 x 2 | 8.000 | 6.375 | 5,000 | H2S | 306-4043-000 |
| 13.000-4 | 9.500 | 7.375 | 10,000 | H2S | 306-4047-000 |
| 13.500-4 | 10.000 | 7.375 | 10,000 | H2S | 306-4048-000 |